

Serviced by: By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.

Joyet Cuevas, Rex Nallas I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.

DANIEL BRUNOS

Created by:
ALVIN DE RIVERA

tion.

Customer
(Signature over printed name)

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 0852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph     

TPWR 34710

SERVICE JOB REPORT

HO-00166294

No.
Previous SJR No.

Customer	Chua Yap, Efren				Date	08-10-2023				
Address	#50 Isarog St. cor Maria Clara, Brgy. Sta. Mesa Heights, QUEZON CITY, Metro Manila...				Start Time	07:43 am				
Telephone No.			Mobile No.			End Time	07:47 am			
Contact Person	Maam Le Slong	Mobile No.		Tel. No.	365-4562	Warranty Type	C			
Warranty Code				Room Size			Job Class	GC	LVL	1
Model	KAG-120RS			Call Origin	IO		Job Type	FD		
S/N (I)	13631408-21014		S/N (O)			Permit? <input type="checkbox"/> Parking? <input checked="" type="checkbox"/> Appointment? <input checked="" type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>		
Dealer	KMI		DOP	Notes *Last GC - June 20, 2022						
Installer			Complaint	For General Cleaning						
Location	BEDROOM		Before	After						
Mode Setting (Cool)			COOL		No. of Visit	1st action	Tentative Sched		08/16/2023	
WAC Setting Temp(16°C-RE)/(10/12-ME)			16°C	Findings						
SAC/PAC Setting Temp (17°)			17°C	DIXY UNIT						
Discharge Temperature (High)			13°C							
Intake Temperature (High)			26°C							
Ampere			4.5A	Recommendation						
Wattage (Inverter)			230W	CLEAN AIR FILTER REGULARLY						
Voltage										
SAC/PAC Pressure (PSI)										
Part Code	Description					Qty	Unit Price	Amount		
SR No.						Labor	800.00			
Repair Done	GENERAL CLEANING					Handling				
Repair Code						Others				
Date Attended	8-16-23		Date Finished	8-16-23		Total	800.00			
Time Attended	9:20		Time Finished	4:35 PM		Amount Paid				
This serves as temporary receipt when properly filled up by authorized representative.					Check No.	TON COLLECTIVE (c/o ICM)		Balance	800.00	
Serviced by:			By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.							
Joyel Cuevas, Rex Nallas			I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
BENASOS		DARREL	Created by: ALVIN DE RIVERA CSR		Conformed by:					
Technician(s)							Customer (Signature over printed name)			

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph     

SERVICE JOB REPORT

3411
 HO-00166295

No.
 Previous SJR No.

Customer	Chua Yap, Efren				Date	08-10-2023				
Address	#50 Isarog St. cor Maria Clara, Brgy. Sta. Mesa Heights, QUEZON CITY, Metro Manila...				Start Time	07:44 am				
Telephone No.			Mobile No.			End Time	07:47 am			
Contact Person	Maam Le Slong	Mobile No.		Tel. No.	365-4562	Warranty Type	C			
Warranty Code				Room Size			Job Class	GC	LVL	1
Model	KAG-210RS			Call Origin	IO	Job Type	FD			
S/N (I)	13651507-13578		S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer	KMI		DOP	Notes *Last GC - June 20, 2022						
Installer			Complaint	For General Cleaning						
Location	BEDROOM #1		Before	After						
Mode Setting (Cool)			COOL	No. of Visit	1st action	Tentative Sched	08/16/2023			
WAC Setting Temp(16°C-RE)/(10/12-ME)			16°C	Findings						
SAC/PAC Setting Temp (17°)			17°C	DIRTY UNIT						
Discharge Temperature (High)			13°C							
Intake Temperature (High)										
Ampere				Recommendation						
Wattage (Inverter)				CLEAN AIR FILTER REGULARLY						
Voltage			230V							
SAC/PAC Pressure (PSI)										
Part Code	Description				Qty	Unit Price	Amount			
SR No.					Labor	800.00				
Repair Done	GENERAL CLEANING				Handling					
Repair Code					Others					
Date Attended	8-16-23	Date Finished	8-16-23	Amount Paid						
Time Attended	9:20 AM	Time Finished	4:35 PM	Balance	800.00					
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	FOR COLLECTION C/O KMI					
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.								
Joyet Cuevas, Rex Nillas		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
BILASOS DARREL		Created by:		Conformed by:						
Technician(s)		ALVIN DE RIVERA								
CSR							Customer (Signature over printed name)			

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph 

SERVICE JOB REPORT

347132

HO-00166296

No. Previous SJR No.


Customer	Chua Yap, Efren				Date	08-10-2023				
Address	#50 Isarog St. cor Maria Clara, Brgy. Sta. Mesa Heights, QUEZON CITY, Metro Manila...				Start Time	07:45 am				
Telephone No.			Mobile No.			End Time	07:47 am			
Contact Person	Maam Le Slong	Mobile No.		Tel. No.	365-4562	Warranty Type	C			
Warranty Code				Room Size			Job Class	GC	LVL	1
Model	KAG-260RS			Call Origin	IO	Job Type	FD			
S/N (I)	13661310-11996		S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input checked="" type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer	KMI		DOP	Notes *Last GC - June 20, 2022						
Installer			Complaint	For General Cleaning						
Location	BEDROOM		Before	After						
Mode Setting (Cool)			COOL		No. of Visit	1st action	Tentative Sched		08/16/2023	
WAC Setting Temp(16°C-RE)/(10/12-ME)			16°C	Findings						
SAC/PAC Setting Temp (17°)			°	DIRTY UNIT						
Discharge Temperature (High)			12°C							
Intake Temperature (High)			25°C							
Ampere			10A	Recommendation						
Wattage (Inverter)				CLEAN AIR FILTER REGULARLY						
Voltage			230V							
SAC/PAC Pressure (PSI)										
Part Code	Description					Qty	Unit Price	Amount		
SR No.						Labor	800 . 00			
Repair Done	GENERAL CLEANING					Handling				
						Others				
Repair Code						Total	800 . 00			
Date Attended	8-16-23		Date Finished	8-16-23		Amount Paid				
Time Attended	9:20		Time Finished	4:35 PM		Balance	800.00			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	FOR COLLECTION		Bank Branch	90 KM		
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.								
Joyel Cuevas, Rex Nallas		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
DULASOS BARREL		Created by:		Conformed by:						
Technician(s)		ALVIN DE RIVERA CSR								

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 0852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph     

34712

SERVICE JOB REPORT

Customer		Chua Yap, Efren		Date	08-10-2023						
Address		#50 Isarog St. cor Maria Clara, , Brgy. Sta. Mesa Heights, QUEZON CITY, Metro Manila...		Start Time	07:50 am						
Manila...				End Time	07:54 am						
Telephone No.			Mobile No.			Relayed by	Caress				
Contact Person	Maam Le Slong	Mobile No.		Tel. No.	365-4562	Warranty Type	C				
Warranty Code			Room Size			Job Class	GC	LVL 1			
Model	KAG-150RSINV		Call Origin	IO	Job Type	FD					
S/N (I)	19021411-10023		S/N (O)			Permit? <input type="checkbox"/>	Parking? <input checked="" type="checkbox"/>	Appointment? <input checked="" type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer	KMI		DOP			Notes *Last GC - June 20, 2022					
Installer			Complaint	For General Cleaning							
Location	BEDROOM	Before	After								
Mode Setting (Cool)			COOL	No. of Visit	1st action	Tentative Sched	08/16/2023				
WAC Setting Temp(16°C-RE)/(10/12-ME)			16°C	Findings							
SAC/PAC Setting Temp (17°)			0	DINGY UNIT							
Discharge Temperature (High)			12°C								
Intake Temperature (High)			25°C								
Ampere			6A	Recommendation							
Wattage (Inverter)			CLEAN AIR FILTER REGULARLY								
Voltage			230V								
SAC/PAC Pressure (PSI)											
Part Code	Description				Qty	Unit Price	Amount				
*KAP-475BHCP											
SN:21021807-10400											
NEED CARBON FILTER											
REPLACED HEPA FILTER					400.00						
*KAP-500CHCPUV											
SN:21032009-10087											
NEED CARBON FILTER											
REPLACED HEPA FILTER					400.00						
*KAP-475BHCP											
SN:21021807-10011											
NEED CARBON FILTER											
REPLACED HEPA FILTER					400.00						
SR No.					Labor	800.00					
Repair Done	GENERAL CLEANING				Handling						
					Others						
Repair Code					Total	800.00					
Date Attended	8-16-23	Date Finished	8-16-23	Amount Paid	1,200.00						
Time Attended	9:20 AM	Time Finished	4:35 PM	Balance	2,000.00						
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	For collection	Bank / Branch	do KMI				
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
Joyel Cuevas, Rex Nolas		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
BLASOS DARREL		Created by:		Conformed by:							
Technician(s)		ALVIN DE RIVERA		Customer (Signature over printed name) 							

Serviced by: **Kolin Philippines International, Inc.** By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.

I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.

JavaGuru - Java Notes

received the unit in good working condition.

soyel Gueyas, Rex Nallas

DATOS BÁSICOS

received the unit in good working condition.

Created by:
ALVIN DE RIVERA CSD

Conformed by:

Customer
(Signature over printed name)

SVC-SJR-02-020123

White - Customer

Blue - Accounting

Green - Service

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph    

SERVICE JOB REPORT

No.
 Previous SJR No.

HO-00166300

Customer	Chua Yap, Efren				Date	08-10-2023					
Address	#50 Isarog St. cor Maria Clara, Brgy. Sta. Mesa Heights, QUEZON CITY, Metro Manila...				Start Time	07:53 am					
Telephone No.			Mobile No.			End Time	07:55 am				
Contact Person	Maam Le Slong	Mobile No.		Tel. No.	365-4562	Warranty Type	C				
Warranty Code				Room Size			Job Class	GC	LVL	1	
Model	WAC-REG			Call Origin	IO		Job Type	FD			
S/N (I)	2 - NATIONAL		S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer			DOP			Notes *Last GC - June 20, 2022					
Installer			Complaint	For General Cleaning							
Location	2ND FLR BEDROOM		Before	After							
Mode Setting (Cool)				No. of Visit	1st action		Tentative Sched	08/16/2023			
WAC Setting Temp(16°C-RE)/(10/12-ME)						Findings					
SAC/PAC Setting Temp (17°)						DIRTY UNIT					
Discharge Temperature (High)											
Intake Temperature (High)											
Ampere						Recommendation					
Wattage (Inverter)						CLEAN AIR FILTER REGULARLY					
Voltage											
SAC/PAC Pressure (PSI)											
Part Code	Description					Qty	Unit Price	Amount			
SR No.						Labor	800.00				
Repair Done	GENERAL CLEANING					Handling					
Repair Code						Others					
Date Attended	8-16-23		Date Finished	8-16-23		Amount Paid					
Time Attended	9:20 AM		Time Finished	4:35 PM		Balance	800.00				
This serves as temporary receipt when properly filled up by authorized representative.					Check No.	FOR COLLECTION				Bank Branch	c/o KM
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
Joyet Cuevas, Rex Nallas		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
BRASOS PARK		Created by:		Conformed by:							
Technician(s)		ALVIN DE RIVERA		Customer (Signature over printed name)							