


CLEARED

34

147

SR No.				Labor	1,20
Repair Done	Installed unit. Test run unit normally			Handling	
	Operation			Others	
Repair Code				Total	1,200.00
Date Attended	August 17, 2023	Date Finished	August 17, 2023	Amount Paid	
Time Attended	10:13 am	Time Finished	11:10 am	Balance	For Collection 6/14 kmh
This serves as temporary receipt when properly filled up by authorized representative.			Check No.	Bank / Branch	
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
  Joshua Concepcion Fernando		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Technician(s)		Created by:	Conformed by:	 Genilo Adty. Jct Customer (Signature over printed name)	
		RÖDEN PULONGBARIT	CSR		

Serviced by: By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.

I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that received the unit in good working condition.

Received the unit in good working condition.

Genilo Adty. Jct
Customer
(Signature over printed name)