

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 0852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph     

TPWR 3473E

SERVICE JOB REPORT

No.	HO-00166872											
Previous SJR No.	HO-00155285											
Customer	Patis College Of Aeronautics		Date	08-14-2023								
Address	Lambo St., Brgy. San Dionisio, PARAÑAQUE CITY, Metro Manila		Start Time	10:55 am								
			End Time	11:00 am								
Telephone No.	825-8823/825-8824	Mobile No.	0995-3650589	Relayed by	Tiffany- Kmi							
Contact Person	...	Mobile No.	0995-3650589	Tel. No.	825-8823/825-8824	Warranty Type	C					
Warranty Code			Room Size			Job Class	INST LVL 2					
Model	KSM-SW25-6H1M32-I		Call Origin	IO	1	Job Type	FD					
S/N (I)			S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>		
Dealer			DOP			Notes (4) KSM-SW25-6H1M32 AREAS: FACULTY DOP: 08/10/2023 EDD: 08/12/2023 DCG REFERRAL COLLECTION C/O KMI WORKING DAYS: MON-SAT, 8AM-5PM WITH PARKING KINDLY ADVISE CLIENT AHEAD OF TIME THANK YOU						
Installer			Complaint	For Installation								
Location	4	Before	After									
Mode Setting (Cool)				No. of Visit	1st Action			Tentative Sched	08/17/2023			
WAC Setting Temp(16°C-RE)/(10/12-ME)						Findings						
SAC/PAC Setting Temp (17°)						7						
Discharge Temperature (High)						1						
Intake Temperature (High)						13						
Ampere						15						
Wattage (Inverter)				for installation		Recommendation 22						
Voltage						1						
SAC/PAC Pressure (PSI)												
Part Code	Description		Qty	Unit Price	Amount							
	ctube 5/8 x 3/8		1/ft	400	\$400							
	b. corn 2.0m x 4C		1/ft	100	\$100							
	b. corn 3.5m x 3C		1/ft	60	\$360							
	c. breaker 30Amp		1/	1,000	\$1,000							
	Installation tools bracket		1									
	fixits type		1									
	clamp (s)		1									
	clamp (d)		1									
	3/4" ribbon		1									
	PVC PIPE 3/4" x 10		1									
SR No.	Initial damage		Labor	\$1,500								
Repair Done	Installation indoor = outdoor unit for start up no power supply		Handling									
Repair Code			Others									
Date Attended	6-17-2023	Date Finished	6-17-2023	Amount Paid	\$8,420							
Time Attended	10:00 AM	Time Finished	4:20 PM	Balance	\$8,420							
This serves as temporary receipt when properly filled up by authorized representative.			Check No.			Bank / Branch	for collection					
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.										
Richard T. Alvarado, Elizion Valle, Medina		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.										
Technician(s)		Created by:		Conformed by:		Customer (Signature over printed name)						
KATHY DE GLZMAN CSR												

Kolin Philippines Int'l., Inc.




1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph    

TPWR 34136

SERVICE JOB REPORT

HO-00166874

HO-00155285

Customer	Patts College Of Aeronautics				Date	08-14-2023					
Address	, Lambo St., Brgy. San Dionisio, PARAÑAQUE CITY, Metro Manila				Start Time	11:00 am					
					End Time	11:03 am					
Telephone No.	825-8823/825-8824		Mobile No.	0995-3650589		Relayed by	Tiffany- Kmi				
Contact Person	...	Mobile No.	0995-3650589	Tel. No.	825-8823/825-8824	Warranty Type	C				
Warranty Code				Room Size		Job Class	INST	LVL 2			
Model	KSM-SW25-6H1M32-I			Call Origin	10 - +	Job Type	FD				
S/N (I)			S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer			DOP			Notes (4) KSM-SW25-6H1M32 AREAS: FACULTY DOP: 08/10/2023 EDD: 08/12/2023 DCC REFERRAL COLLECTION C/O KMI WORKING DAYS: MON-SAT, 8AM-5PM WITH PARKING KINDLY ADVISE CLIENT AHEAD OF TIME THANK YOU!					
Installer			Complaint	For Installation							
Location	2	Before	After								
Mode Setting (Cool)				No. of Visit	1st Action	Tentative Sched		08/17/2023			
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings							
SAC/PAC Setting Temp (17°)											
Discharge Temperature (High)											
Intake Temperature (High)											
Ampere				Recommendation							
Wattage (Inverter)				For Installation							
Voltage											
SAC/PAC Pressure (PSI)											
Part Code	Description				Qty	Unit Price	Amount				
	C. tube 1/8 x 3/8				11 ft	400	400				
	P. COTN 2.0mm x 40				18 ft	100	800				
	P. COTN 3.5m x 30				7	60	420				
	C. Breaker 70Amp				1	1,000	1,000				
	Installation Floor bracket				1						
	Chickness tape				1						
	Clamp (s)				10						
	PVC tube 3/4				2						
	Clamp (s)				10						
	PVC pipe 3/4 x 10				1						
	Troph 1232				1						
SR No.	30969 INITIAL CHANGE				Labor		5,500				
Repair Done	Installation indoor & outdoor unit for start-up, NO power supply				Handling						
Repair Code					Others						
Date Attended	8-17-2023		Date Finished	8-17-2023		Amount Paid					
Time Attended	10:00 am		Time Finished	4:20 pm		Balance		8,120			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		for collection				
Serviced by:  		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
Richard Telavera, Ericson Valle, Ch Medina		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
Technician(s)		Created by: 	CSR	Conformed by: 		Customer (Signature over printed name)					

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No.: 0882-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph     

+PWR 347347

SERVICE JOB REPORT

HO-00166876

HO-00155285



Customer	Patis College Of Aeronautics				Date	08-14-2023					
Address	, Lambo St., Brgy. San Dionisio, PARANAQUE CITY, Metro Manila				Start Time	11:03 am					
					End Time	11:04 am					
Telephone No.	825-8823/825-8824	Mobile No.	0995-3650589		Relayed by	Tiffany- Kmi					
Contact Person	...	Mobile No.	0995-3650589	Tel. No.	825-8823/825-8824	Warranty Type	C				
Warranty Code			Room Size			Job Class	INST LVL 2				
Model	KSM-SW25-6H1M32-I		Call Origin	IO		Job Type	FD				
S/N (I)			S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer			DOP			Notes (4) KSM-SW25-6H1M32 AREAS: FACULTY DOP: 08/10/2023 EDD: 08/12/2023 DCC REFERRAL COLLECTION C/O KMI WORKING DAYS: MON-SAT, 8AM-5PM WITH PARKING KINDLY ADVISE CLIENT AHEAD OF TIME THANK YOU.					
Installer			Complaint	For Installation							
Location	3	Before	After								
Mode Setting (Cool)				No. of Visit	1st Action	Tentative Sched		08/17/2023			
WAC Setting Temp(16°C-RE)/(10/12-ME)						Findings					
SAC/PAC Setting Temp (17°)											
Discharge Temperature (High)											
Intake Temperature (High)											
Ampere						Recommendation					
Wattage (Inverter)						for Installation					
Voltage											
SAC/PAC Pressure (PSI)											
Part Code	Description				Qty	Unit Price	Amount				
	c. tube 5/8 x 3/8				15 ft	400	2,000				
	1. corn 12m x 40				22 ft	100	1,200				
	1. corn 3.5m x 30				7 ft	60	420				
	c. bracket 30mm				1	1,000	1,000				
	installation foot bracket				1						
	sicklass				1						
	clamp (s)				10						
	clamp (0)				10						
	pvc elbow 3/4				12						
	pvc pipe 3/4 x 10				1						
REQUOTED											
SR No.	30970				Labor	5,500					
Repair Done	install indoor / & outdoor unit for start up / no power supply				Handling						
Repair Code					Others						
Date Attended	8-17-2023	Date Finished	8-17-2023		Amount Paid						
Time Attended	10:20 AM	Time Finished	4:20 PM		Balance	10,120					
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch				for collection		
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
Richard Talavera, Ericson Valle, O. Medina		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
Vahli Barratah		Created by:		Conformed by:		John Edward C. Cuizon					
Technician(s)		KATHY DE GUZMAN				Customer (Signature over printed name)					
CSR											

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 0852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph     

TPWR-34738

SERVICE JOB REPORT

No.	HO-00166877										
Previous SJR No.	HO-00155285										
Customer	Patts College Of Aeronautics		Date	08-14-2023							
Address	Lambo St., Brgy. San Dionisio, PARANAQUE CITY, Metro Manila		Start Time	11:06 am							
			End Time	11:07 am							
Telephone No.	825-8823/825-8824	Mobile No.	0995-3650589	Relayed by	Tiffany- Kmi						
Contact Person	...	Mobile No.	0995-3650589	Tel. No.	825-8823/825-8824	Warranty Type	C				
Warranty Code			Room Size			Job Class	INST LVL 2				
Model	KSM-SW25-6H1M32-I		Call Origin	IO +		Job Type	FD -				
S/N (I)			S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer			DOP			Notes (4) KSM-SW25-6H1M32 AREAS: FACULTY DOP: 08/10/2023 EDD: 08/12/2023 DCG REFERRAL COLLECTION C/O KMI WORKING DAYS: MON-SAT, 8AM-5PM WITH PARKING KINDLY ADVISE CLIENT AHEAD OF TIME THANK YOU.					
Installer			Complaint	For Installation							
Location	1	Before	After								
Mode Setting (Cool)				No. of Visit	1st Action			Tentative Sched	08/17/2023		
WAC Setting Temp(16°C-RE)/(10/12-ME)						Findings					
SAC/PAC Setting Temp (17°)											
Discharge Temperature (High)											
Intake Temperature (High)											
Ampere						Recommendation					
Wattage (Inverter)											
Voltage											
SAC/PAC Pressure (PSI)											
Part Code	Description				Qty	Unit Price	Amount				
	C. TUBE 18 x 3/8				1/4#	400	1,600				
	D. COTRY 2.0mm x 4C				21#	100	1,100				
	R. CONN 3.5mm x 3C				6#	60	360				
	Installation tool bracket				1	—	—				
	C. Breaker 30Amp				1	1,000	1,000				
	Stockless tape				1	—	—				
	Clamp (S)				1	—	—				
	Clamp (D)				1	—	—				
	PVC 1 1/2" 3/4 x 10				1	—	—				
	PVC tube 3/4				2	—	—				
SR No.	30934				Labor	5,500					
Repair Done	Installation indoor / & outdoor unit				Handling	—					
	for start up / no power supply				Others	—					
Repair Code					Total	9,500					
Date Attended	8-17-2023	Date Finished	8-17-2023	Amount Paid					—		
Time Attended	10:00 AM	Time Finished	4:20 PM	Balance					9,500		
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch					Collector	
Serviced by: 		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
Richard Talavera, Ericson Valla, O. Medina		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
Technician(s)		Created by: 	Conformed by: 								
		Customer (Signature over printed name)									