

Customer		Victory Land		No.		HO-00167490	
Address		Wilson Corporate Center, P. Gomez St., Brgy. Addition Hills, SAN JUAN CITY, M...		Previous SJR No.		HO-00166989	
		ro Manila...		Date		08-17-2023	
Telephone No.				Mobile No.		0906-4512228	
Contact Person		Ms. Ann		Mobile No.		0920-1326253	
Warranty Code				Tel. No.		0906-4512228	
Model		KFM-400F1J		Room Size			
S/N (I)		10631407-16709		Call Origin		IO	
Dealer				Job Class		TS LVL 1	
Installer				Job Type		FD	
Location		Before After		Permit? ☐ Parking? ☐ Appointment? ☐ O.R.? ☐ Ladder? ☐			
Mode Setting (Cool)		1202		Notes		VILLAFUERTE Cortez FOR CHECK UP- (NEED REPROCESS ACCORDING TO CUSTOMER) 1 UNIT FAC COLLECTION C/O KMI ASAP KINDLY UPDATE CLIENT AHEAD OF TIME check onsite model KMI, cannot provide exact model	
WAC Setting Temp (16°C-RE)/(10/12-ME)				No. of Visit		1st Action Tentative Sched 08/18/2023	
SAC/PAC Setting Temp (17°)		17		Findings		WEAK COOLING LEAK @ SUCTION GATE VALVE	
Discharge Temperature (High)		30.2		Recommendation		FOR REPLACEMENT OF SUCTION GATE VALVE, FOR 2ND ACTION	
Intake Temperature (High)							
Ampere		10.1					
Wattage (Inverter)							
Voltage		230					
SAC/PAC Pressure (PSI)		20.9					
Part Code		Description		Qty		Unit Price Amount	
NOTE: - ON SITE REPAIR							
- NEED 4 PAX							
- NEED HARNESS							
DATE 8/18/2023							
SR No.				Labor		600	
Repair Done		CHECK UP & GAS PARAMETERS ONLY		Handling			
Repair Code				Others			
Date Attended		8-18-23		Total		600	
Time Attended		12.30		Amount Paid		for collection	
Time Finished		2:15		Balance		40 PM	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Jarry Munday, Neil Villafuerte, Marlon Salomon		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s)		Created by: RECHILLA CSR		Conformed by:		Customer (Signature over printed name)	