


Customer	Gakken Phils. Inc (Head Office)					Date	08-15-2023				
Address	130 GPI Bldg., Aurora Blvd Comer A Lake St., Brgy. Salapan, SAN JUAN CITY, Metro Manila...					Start Time	02:36 pm				
Telephone No.	3429-8844 / 7748-7941		Mobile No.	0977-1903459/0905-4340664		End Time	02:39 pm				
Contact Person	Mr. Toni	Mobile No.	917-7082427		Tel. No.	0917-7082427					
Warranty Code				Room Size			Warranty Type	C			
Model	KSG-IWF-30WFY-8K1M32-I			Call Origin	IO		Job Type	FD			
S/N (I)			S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer	KMI		DOP	08/09/2023		Notes TALAVERA 8/19 2ND CUSTOMER BEFORE LUNCH - FOR FABRICATION OF BRACKET - EDD: 8/11/2023 -					
Installer			Complaint	Others		REG CUSTOMER - AREA: 2 FLOOR ONLY - COLLECTION C/O KMI - ASAP					
Location	2/F HR DEPARTMENT		Before	After							
Mode Setting (Cool)				No. of Visit	1st Action		Tentative Sched	08/19/2023			
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings							
SAC/PAC Setting Temp (17°)											
Discharge Temperature (High)											
Intake Temperature (High)											
Ampere				Recommendation							
Wattage (Inverter)				+ for + for O.D. BRACKET							
Voltage											
SAC/PAC Pressure (PSI)											
Part Code	Description					Qty	Unit Price	Amount			
											
SR No.						Labor	2,500				
Repair Done	+ for. OUTDOOR bracket					Handling					
						Others					
Repair Code						Total	2,500				
Date Attended	8-19-2023	Date Finished	8-19-2023		Amount Paid						
Time Attended	10:00 AM	Time Finished	1:40 PM		Balance		2,500				
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			Bank / Branch	For collection			
Serviced by: <u>Colomon</u> <u>Richard Talavera, Ericson Valle, C. Medina</u>		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
Technician(s)		Created by: <u>RECHILLA</u>		Conformed by: <u>RECHILLA</u> for 8/19/2023 Customer (Signature over printed name)							

HO-00167188

HO-00164690

Customer	Gakken Phils. Inc (Head Office)				Date	08-15-2023								
Address	130 GPI Bldg., Aurora Blvd Corner A Lake St., , Brgy. Salapan, SAN JUAN CITY				Start Time	01:48 pm								
Metro Manila...					End Time	01:52 pm								
Telephone No.	8429-8844 / 7748-7941		Mobile No.	0977-1903459/0905-4340664		Relayed by	KMI- Jozelle							
Contact Person	Mr. Toni	Mobile No.	0917-7082427	Tel. No.	0917-7082427	Warranty Type	C							
Warranty Code				Room Size			Job Class	INST						
Model	KSG-IWF-30WFY-8K1M32-I			Call Origin	IO	Job Type	FD							
S/N (I)	18512303-137197	S/N (O)	18522303-135791	Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>	Appointment?	<input type="checkbox"/>	O.R.?	<input type="checkbox"/>	Ladder?	<input type="checkbox"/>	
Dealer	KMI		DOP	08/09/2023		Notes	TALAVERA 8/19 2ND CUSTOMER BEFORE LUNCH - EDD: 8/11/2023 - REG CUSTOMER - AREA 2 FLOOR							
Installer			Complaint	For Installation		ONLY - COLLECTION C/O KMI - ASAP								
Location	2/F HR DEPARTMENT		Before	After										
Mode Setting (Cool)				No. of Visit	1st Action		Tentative Sched		08/19/2023					
WAC Setting Temp(16°C-RE)/(10/12-ME)	Findings													
SAC/PAC Setting Temp (17°)														
Discharge Temperature (High)														
Intake Temperature (High)														
Ampere	Recommendation													
Wattage (Inverter)	for Installation													
Voltage														
SAC/PAC Pressure (PSI)														
Part Code	Description				Qty	Unit Price	Amount							
	c. tube 5/8 x 16				15FT	400	\$ 2,000							
	l. cord 2.0mm x 40				21FT	100	\$ 1,200							
	l. cord 35m x 30				7Ft	600	\$ 1,420							
	c. breaker 30Amp				1	1000	\$ 1,000							
	Stainless type				2									
	Clamp (S)				1									
	Clamp (D)				1									
	Duct PIPE 3/4 x 10				1									
	furon 3/2				1									
LIQUIDATED 8/19/2023														
SR No.	31029 Initial Cleaning				Labor		\$ 4,700							
Repair Done	Installation indoor & outdoor unit				Handling		\$ 0							
	Start up / Testing & run unit				Others		\$ 0							
Repair Code	Normal Operation				Total		\$ 9,320							
Date Attended	8.19.2023	Date Finished	8.19.2023	Amount Paid		\$ 0								
Time Attended	10:00 AM	Time Finished	1:40 PM	Balance		\$ 9,320								
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		for collection							
Serviced by:	DAR5659		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.											
Richard Tavera, Ericson Valla, G. Medina				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.										
Monday		SOLomon		Created by: RECHILLA		Conformed by: NEHA SHAP		Customer (Signature over printed name) 8/19						
Technician(s)		CSR												

