

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph  kolinphilippines

~~CLEARED~~ BY ~~DA-12~~ 8/9/2017

SR No.				Labor	2,000
Repair Done	Conduct general cleaning indoor & outdoor unit. Test run unit normally operation			Handling	
				Others	
Repair Code				Total	2,000.00
Date Attended	August 19, 2023	Date Finished	August 19, 2023	Amount Paid	
Time Attended	11:30 AM	Time Finished	2:00 pm	Balance	For Collection
This serves as temporary receipt when properly filled up by authorized representative.			Check No.	Bank / Branch	
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Albon Tuan		Created by:	Conformed by:		
Technician(s)		KATHY DE GUZMAN CSR	Customer (Signature over printed name)		

K Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph      

TPNR 34794

SERVICE JOB REPORT

No. **HO-00166803**
Previous SJR No. **HO-00166806**

Customer	Omnibus Bio Medical System				Date	08-14-2023	
Address	4/F Wilson Corporate Center, 225 Wilson St., Brgy. Greenhills, SAN JUAN CITY, Metro Manila...				Start Time	10:43 am	
Telephone No.			Mobile No.	0966-8849002	End Time	10:44 am	
Contact Person	Ms. Joyce	Mobile No.		Tel. No.	Relayed by Inzelle- KMI		
Warranty Code				Room Size	Warranty Type C		
Model	KFM-400GF1INV			Call Origin IO	Job Class GC	LVL 1	Job Type FD
S/N (I)	10941408-11351	S/N (O)		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>		
Dealer	DOP			Notes Lopez CONTACT PERSON: MS. JOYCE 0966-8849002 UNIT MODEL: KFM-400GF1INV 4 UNITS COLLECTION C/O KMI REQUEST SCHEDULE SATURDAY KINDLY ADVISE CLIENT AHEAD OF TIME.			
Installer	Complaint For General Cleaning						
Location	Before	After		No. of Visit 1st Action	Tentative Sched	08/19/2023	
Mode Setting (Cool)	201	201		Findings Dirty Unit			
WAC Setting Temp(16°C-RE)/(10/12-ME)							
SAC/PAC Setting Temp (17°)	24°	17°					
Discharge Temperature (High)	14.5	13.8					
Intake Temperature (High)	25.1	24.7					
Ampere	15.1	16.5		Recommendation			
Wattage (Inverter)				For cleaning			
Voltage	175	205					
SAC/PAC Pressure (PSI)	140	140					
Part Code	Description			Qty	Unit Price	Amount	
SR No.					Labor	2,000.00	
Repair Done	Conduct general cleaning indoor & outdoor unit. Test run unit normally operation				Handling		
Repair Code					Others		
Date Attended	August 19, 2023	Date Finished	August 19, 2023	Amount Paid	2,000.00		
Time Attended	11:15 AM	Time Finished	2:00 PM	Balance	For collection c/o KMI		
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Alben		Created by: Conformed by: Customer (Signature over printed name)					
Technician(s)		KATHY DE GUAZMAN					



~~CLEARED~~

8/19/2012

SR No.				Labor	2,000
Repair Done	Conduct general cleaning indoor & outdoor unit, Test run unit normally operation			Handling	
				Others	
Repair Code				Total	₱ 2,000.00
Date Attended	August 19, 2023	Date Finished	August 19, 2023	Amount Paid	
Time Attended	11:30 am	Time Finished	2:00 pm	Balance	For collection clif
This serves as temporary receipt when properly filled up by authorized representative.			Check No.	Bank / Branch	KMI
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
Fernando Lopez, Kevin Senar		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Trwin	Alben	Created by: KATHY DE GUZMAN CSR	Conformed by: <i>new customer</i>	Customer ..(Signature over printed name)	
Technician(s)					

Kolin Philippines Int'l., Inc.


1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph     

TPWR-34796

SERVICE JOB REPORT

HO-00166887

HO-00155308

Customer	Omnibus Bio Medical System				Date	08-14-2023				
Address	4/F Wilson Corporate Center, 225 Wilson St., Brgy. Greenhills, SAN JUAN CITY, Metro Manila...				Start Time	11:28 am				
Telephone No.			Mobile No.	0966-8849002	End Time	11:29 am				
Contact Person	Ms. Joyce	Mobile No.	Tel. No.		Relayed by	Jozelle- KMI				
Warranty Code			Room Size		Warranty Type	C				
Model	KSM-300B1H		Call Origin	O	Job Class	GC	LVL			
S/N (I)	(6091408 - 113)		S/N (O)		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input checked="" type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer			DOP		Notes Lopez CONTACT PERSON: MS. JOYCE-0966-8849002 UNIT MODEL : KFM-400GF1INV 4					
Installer			Complaint	For General Cleaning	UNITS COLLECTION C/O KMI REQUEST SCHEDULE SATURDAY KINDLY ADVISE CLIENT AHEAD OF TIME.					
Location			Before	After						
Mode Setting (Cool)	(w)		(w)	No. of Visit	1st Action	Tentative Sched		08/19/2023		
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings						
SAC/PAC Setting Temp (17°)	24°		17°	Dirty Unit						
Discharge Temperature (High)	15.5		13.5							
Intake Temperature (High)	25.7		24.8							
Ampere	8.7		10.5	Recommendation						
Wattage (Inverter)				For Cleaning						
Voltage	225		225							
SAC/PAC Pressure (PSI)	(60)		65							
Part Code	Description				Qty	Unit Price	Amount			
SR No.					Labor	1,700				
Repair Done	Conduct Cleaning indoor & outdoor unit, test run unit normally operation				Handling					
					Others					
Repair Code					Total	1,500.00				
Date Attended	August 19, 2023	Date Finished	August 19, 2023	Amount Paid						
Time Attended	11:19 am	Time Finished	2:00 pm	Balance						
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch					
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.								
Fernando Lopez, Kevin Senar		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
Alben		Created by: KATHY DE GUZMAN CSR		Conformed by:  Customer (Signature over printed name)						
Technician(s)										

