

Customer		Tuquib, Raphie		No.		HO-00187661	
Address		Rm. 1401 State Center Bldg., 333 Juan Luna St., Brgy. Binondo (Near Binondo Church), MANILA CITY, Metro Manila...		Previous SJR No.			
Telephone No.		8242-0829		Mobile No.		0917-8324211	
Contact Person		Ms. Graciela/ Raphie		Tel. No.		8242-0829	
Warranty Code				Room Size			
Model		n/a		Call Origin		IO	
S/N (I)				S/N (O)			
Dealer				DOP			
Installer				Complaint		For Survey	
Location		For Survey		Before		After	
Mode Setting (Cool)				No. of Visit		1st Action	
WAC Setting Temp (16°C-RE)/(10/12-ME)				Tentative Sched		02/14/2024	
SAC/PAC Setting Temp (17°)				Findings			
Discharge Temperature (High)				Recommendation			
Intake Temperature (High)				Room 1 2.5 hp			
Ampere							
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		Sign wire 700					
		Power supply wire 450					
		Breaker 1000					
		hvac log 5500					
		Total 7 620					
SR No.				Labor		500	
Repair Done				Handling			
Repair Code				Others			
Date Attended		2-14-24		Date Finished		2-14-24	
Time Attended				Time Finished			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: Jeffrey Dadios		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s)		LUIS REBUYAS CSR		Conformed by:		Customer (Signature over printed name)	