

No.  
Previous SJR No.HO-00167938  
HO-00165769





Customer	Uyslpuo, Fred				Date	08-22-2023				
Address	654 Richmond St., Brgy. Greenhills East, MANDALUYONG CITY, Metro Manila				Start Time	10:17 am				
					End Time	10:25 am				
Telephone No.	88725-0026		Mobile No.	0917-8162271		Relayed by	KMI- Tiffany			
Contact Person	Charlene/ Fred	Mobile No.	0917-8162271	Tel. No.	02-88725-0026	Warranty Type	C			
Warranty Code			Room Size			Job Class	GC	LVL 1		
Model	KSM-20MB4INV KSM-24CS1C		Call Origin	IO		Job Type	FD			
S/N (I)	10891506-17247		S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer			DOP			Notes VILLAFUERTE - SCHEDULE ASAP - KC REFERRAL - KINDLY ASK CLIENT FOR THE EXACT MODEL				
Installer			Complaint	For General Cleaning						
Location	Boy's Room	Before	After							
Mode Setting (Cool)				No. of Visit	1st Action	Tentative Sched	08/25/2023			
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Findings						
SAC/PAC   Setting Temp (17°)				low BLOW fan, DRAFT UNIT						
Discharge Temperature (High)										
Intake Temperature (High)										
Ampere				Recommendation						
Wattage (Inverter)				fan G.C						
Voltage										
SAC/PAC   Pressure (PSI)										
Part Code	Description				Qty	Unit Price	Amount			
SR No.					Labor	\$ 2,800				
Repair Done	G.C. Testing & Run UPIT				Handling					
	NORMAL OPERATION				Others					
Repair Code					Total	\$ 2,800				
Date Attended	8-23-23	Date Finished	8-23-23	Amount Paid						
Time Attended	12:39 pm	Time Finished	4:00 pm	Balance	\$ 2,800					
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			Bank / Branch	for collection		
Serviced by: <i>Valveva Mendoza</i>		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.								
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
Technician(s) <i>Barry Munday, Neil Villafuerte, Mar Salomon</i>		Created by: <b>RÖDEN PULONGBARIT</b> CSR		Conformed by: <i>Valveva Mendoza</i>						

# Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
 Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph  
 Website: www.kolinphil.com.ph     

TPWR 34846

## SERVICE JOB REPORT

No.	HO-00167939								
Previous SJR No.	HO-00165789								
Customer	Uyslpuo, Fred		Date	08-22-2023					
Address	654 Richmond St., Brgy. Greenhills East, MANDALUYONG CITY, Metro Manila		Start Time	10:17 am					
			End Time	10:26 am					
Telephone No.	88725-0026	Mobile No.	0917-8162271	Relayed by	KMI- Tiffany				
Contact Person	Charlene/ Fred	Mobile No.	0917-8162271	Tel. No.	02-88725-0026	Warranty Type	C		
Warranty Code			Room Size			Job Class	GC	LVL	1
Model	KSM-30MB1INV		Call Origin	IO		Job Type	FD		
S/N (I)	18011506-11391	S/N (O)	10901506-16505	Permit? <input type="checkbox"/>	Parking? <input checked="" type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer			DOP			Notes	VILLAFUERTE - SCHEDULE ASAP - KC REFERRAL - KINDLY ASK CLIENT FOR THE EXACT MODEL 2245		
Installer			Complaint	For General Cleaning					
Location	Master's Bedroom	Before	After						
Mode Setting (Cool)	106			No. of Visit	1st Action	Tentative Sched	08/25/2023		
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Findings					
SAC/PAC   Setting Temp (17°)	19			DIRTY UNIT					
Discharge Temperature (High)	19								
Intake Temperature (High)	24								
Ampere	7.9			Recommendation					
Wattage (Inverter)									
Voltage	230			6.0					
SAC/PAC   Pressure (PSI)	140PS								
Part Code	Description				Qty	Unit Price	Amount		
SR No.							Labor	1,500	
Repair Done	S.C. Testing & run, UNIT Normal Operation						Handling		
Repair Code							Others		
Date Attended	8-23-23	Date Finished	8-23-23	Total 1,500					
Time Attended	11:31	Time Finished	4:00 pm	Amount Paid 1,500					
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Balance 1,500				
Serviced by: 		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.							
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Technician(s) 		Created by: 		Conformed by: 					
		RODEN PULONGBARIT CSR		Customer (Signature over printed name)					

# Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph  
Website: www.kolinphil.com.ph 

TPWk 24847

## SERVICE JOB REPORT

HO-00167940

No.  
Previous SJR No.

HO-00165789

Customer	Uysipuo, Fred				Date	08-22-2023				
Address	654 Richmond St., Brgy. Greenhills East, MANDALUYONG CITY, Metro Manila				Start Time	10:17 am				
					End Time	10:26 am				
Telephone No.	88725-0026	Mobile No.	0917-8162271		Relayed by	KMI- Tiffany				
Contact Person	Charlene/ Fred	Mobile No.	0917-8162271	Tel. No.	02-88725-0026	Warranty Type	C			
Warranty Code				Room Size			Job Class	GC	LVL	1
Model	KSM-25MB1INV			Call Origin	IO		Job Type	FD		
S/N (I)	10911506-15991	S/N (O)	1		Permit? <input type="checkbox"/> Parking? <input checked="" type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>		
Dealer	KITCHEN	DOP			Notes VILLAFUERTE - SCHEDULE ASAP - KC REFERRAL - KINDLY ASK CLIENT FOR THE EXACT MODEL					
Installer			Complaint	For General Cleaning						
Location	BEDROOM / GIRLS ROOM NO. 2	Before	After							
Mode Setting (Cool)	Cool			No. of Visit	1st Action	Tentative Sched		08/25/2023		
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Findings						
SAC/PAC   Setting Temp (17°)	17			low blow fan, dirty unit						
Discharge Temperature (High)	19									
Intake Temperature (High)	30									
Ampere	12.1			Recommendation						
Wattage (Inverter)										
Voltage	220			fan 60						
SAC/PAC   Pressure (PSI)	140PS									
Part Code	Description				Qty	Unit Price	Amount			
SR No.					Labor	1,500				
Repair Done	G.C. testing & run - up				Handling					
	Normal Operation				Others					
Repair Code					Total	1,500				
Date Attended	8.23.23	Date Finished	8.23.23		Amount Paid					
Time Attended	10:39 AM	Time Finished	4:00 PM		Balance	1,500				
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch					
Serviced by: <i>Technician</i> Incina		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.								
Barry Mundoy, Neil Villafuerte, Ma. Balonan		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
Technician(s)		Created by: RODEN PULONGBARIT	CSR	Conformed by: <i>ahrye</i>						
				Customer (Signature over printed name)						