

Customer		Cua, Dr. Irwin		Date		08-22-2023	
Address		Unit 1410 Rosemont Tower, 75 Panay Ave., Brgy. Diliman, QUEZON CITY, Metro Manila		Start Time		10:27 am	
la...				End Time		10:30 am	
Telephone No.				Mobile No.		0917-5337575	
Contact Person		Dr. Irwin		Tel. No.		0917-5337575	
Warranty Code				Room Size			
Model		KSM-SW20-5G1M		Call Origin		IO	
S/N (I)		16172011-11814		S/N (O)		16181910-11072	
Dealer		KMI		DOP		05/04/2021	
Installer		Reymon Leyls		Complaint		Noisy	
Location		BEDROOM		Before		After	
Mode Setting (Cool)				No. of Visit		1st Action	
WAC Setting Temp(16°C-RE)/(10/12-ME)				Tentative Sched		08/24/2023	
SAC/PAC Setting Temp (17°)				Findings			
Discharge Temperature (High)				Damaged blower wheel - vibration			
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)				for 2nd action			
Voltage				Bring Blower wheel, per (100) and fan motor			
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		Bring All possible parts.					
SR No.				Labor		450-	
Repair Done		check-up only - for 2nd action		Handling			
Repair Code				Others			
Date Attended		08-24-23		Total		450-	
Time Attended		0940H		Amount Paid		payment upon completion	
Date Finished		08-24-23		Balance			
Time Finished		1000H		Bank / Branch			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Joshua Cortez Vishn		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Bogart		Created by:		Conformed by:			
Technician(s)		RODEN PULONGBARIT CSR		Customer (Signature over printed name)			